

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE.

No. S.H./2022/ 193

Date : 16-12-2022

It is certified that an inspection team headed by Dr Shailender Kumar, Dy Civil surgeon, Gurugram and inspection done by Dr. Shailender Kumar, Nodal Officer School health, Gurugram of DAV Senior Secondary School Khandsa Road, Gurugram, 12-12-2022 and found that the, DAV Senior Secondary School Khandsa Road, Gurugram has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T Govt.

The above valid for a period of One Year.

Signature with Seal:

Name:

Designation:

CIVIL SURGEON  
GURUGRAM

To

DAV Senior Secondary School Khandsa Road,  
Gurugram

Principal  
D.A.V. Sr. Sec. School  
Khandsa Road, Gurgaon